

**BESTWAY TIRES & AUTOMOTIVE CENTRE**  
 9927-51 Avenue  
 Edmonton, Alberta T6E 0A8  
 Ph.: (403) 435-6400  
 Fax: (403) 434-5173

NAME \_\_\_\_\_  
 ADDRESS \_\_\_\_\_  
 PHONE: (Bus) \_\_\_\_\_ (Res) \_\_\_\_\_

VEHICLE INFORMATION

|                                   |                            |   |                                    |  |                  |
|-----------------------------------|----------------------------|---|------------------------------------|--|------------------|
| VEHICLE MAKE<br><i>ALFA ROMEO</i> | MODEL<br><i>SPIDER</i>     | TYPE<br><i>2dr conv</i>                   | YEAR<br><i>69</i>                  | VI. NUMBER                                   | ODOMETER READING |
| # OF CYLINDERS<br><i>4</i>        | ENGINE SIZE<br><i>1750</i> | CARBURETOR<br><i>Mechanical Fuel Inj.</i> | TRANSMISSION                       |  |                  |
|                                   |                            |   | <input type="checkbox"/> AUTOMATIC | <input checked="" type="checkbox"/> STANDARD |                  |

REPAIR ESTIMATE

| ELECTRICAL ACCESSORIES |  |
|------------------------|--|
| 1                      | BATTERY: Electrolyte Level / Case / Hold-Down / Terminals / Cables / Load Test ✓ |
| 2                      | SWITCHES: Ignition/Lights / Dimmer / Signal 4 Way / Wiper ✓                      |
| 3                      | INSTRUMENTS / Horn ✓   |
| 4                      | HEAD LIGHTS: High R/L Low R/L ✓  |
| 5                      | TAIL LIGHTS: R/L ✓   |
| 6                      | STOP LIGHTS: R/L ✓   |
| 7                      | LICENCE PLATE LIGHT ✓  |
| 8                      | BACK-UP LIGHTS: R/L ✓  |
| 9                      | TURN SIGNALS: RF/LF/RR/RL ✓  |
| 10                     | TURN SIGNALS: Cancel R/L ✓   |
| 11                     | MARKER LIGHTS: RF/LF/RR/RL ✓   |
| 12                     | EMERGENCY FLASHER ✓  |
| 13                     | PARK LIGHTS: RF/LF/RR/RL ✓   |
| 14                     | WIPERS: Motor / Blades / Arms / F/R ✓  |
| 15                     | WINDSHIELD WASHERS: F/R ✓  |
| 16                     | AC / HEATER / DEFROST Operation ✓  |
| 17                     | INTERIOR LIGHTS ✓  |
| 18                     | RADIO / ANTENNA ✓  |
| 19                     | POWER WINDOWS: RF/LF/RR/LR ✓   |
| 20                     | POWER SEATS ✓  |
| 21                     | ALTERNATOR / STARTER Operation ✓   |
| 22                     | REGULATOR ✓  |
| 23                     | REAR DEFOGGER ✓  |

| ENGINE |   |
|--------|---|
| 45     | OIL: Level / Condition ✓                |
| 46     | FREEZE PLUGS: Leaks / Corroded ✓        |
| 47     | VALVE COVERS: R/L Leaks ✓               |
| 48     | THIMING COVER / Front Seal Area Leaks ✓ |
| 49     | PAN / GASKET Leaks ✓                    |
| 50     | FUEL PUMP Leaks/Oil/Fuel ✓              |
| 51     | OIL FILTER Leaks ✓                      |
| 52     | REAR SEAL AREA Oil Leaks ✓              |
| 53     | INTAKE MANIFOLD Condition / Leaks ✓     |
| 54     | OIL PRESSURE SENDER Unit ✓              |
| 55     | VALVE Noise ✓                           |
| 56     | ENGINE Noise ✓                          |
| 57     | MOTOR: Cleanliness ✓                    |
| 58     | ENGINE MOUNTS R/L ✓                     |
| 59     | BELTS P/S A/C / Air Pump / Alt. ✓       |
| 60     | PULLEYS: Condition ✓                    |
| 61     | BLOW-BY ✓                               |
| 62     | ENGINE OIL (Burning) ✓                  |
| 63     | IGNITION SYSTEM ✓                       |
| 64     | CYLINDER BALANCE ✓                      |

| DRIVELINE |   |
|-----------|---|
| 92        | CLUTCH FLUID - Level / Leaks ✓                  |
| 93        | AUTO TRANS. FLUID - Level / Condition ✓         |
| 94        | CLUTCH PEDAL / LINKAGE OPERATION / Adjustment ✓ |
| 95        | "U" JOINTS: Front / Center / Rear ✓             |
| 96        | "U" JOINTS: Inner R/L ✓                         |
| 97        | "U" JOINTS: Outer R/L ✓                         |
| 98        | C.V. JOINT R/L ✓                                |
| 99        | C.V. JOINT RUBBER BOOT R/L ✓                    |
| 100       | DRIVE SHAFT BOOT R/L ✓                          |
| 101       | TRANSMISSION MOUNTS ✓                           |
| 102       | DIFFERENTIAL MOUNTS ✓                           |
| 103       | AXLE BEARINGS: R/L ✓                            |
| 104       | AXLE SEAL Leaks R/L ✓                           |
| 105       | TRANSMISSION REAR BUSHING ✓                     |
| 106       | SPEEDO DRIVE Leaks ✓                            |
| 107       | TRANS. REAR SEAL FLANGE Leaks ✓                 |
| 108       | TRANS. SHIFT SEAL Leaks ✓                       |
| 109       | TRANS. FRONT SEAL Leaks ✓                       |
| 110       | TRANS. OIL PAN - Condition / Leaks ✓            |
| 111       | TRANS. OIL COOLER LINE Leaks ✓                  |
| 112       | TRANSMISSION SERVO Leaks ✓                      |
| 113       | DIFFERENTIAL PINION GASKET Leaks ✓              |
| 114       | DIFFERENTIAL COVER GASKET Leaks ✓               |
| 115       | SHIFT INDICATOR / LINKAGE ✓                     |
| 116       | AXLE SHAFT SEAL Inner/Outer R/L ✓               |
| 117       | DRIVE SHAFT Condition ✓                         |
| 118       | DRIVE SHAFT CENTER BEARING ✓                    |

| FRONT SUSPENSION & STEERING |  |
|-----------------------------|--|
| 135                         | ALIGNMENT - Visual ✓                             |
| 136                         | STEERING BOX Adjustment/Leak/Operation ✓         |
| 137                         | STEERING SHAFT COUPLING / BUSHING BEARING ✓      |
| 138                         | STEERING DAMPER Condition / Leaks ✓              |
| 139                         | RACK & PINION Operation / Leaks ✓                |
| 140                         | BALL JOINT Lower R/L ✓                           |
| 141                         | BALL JOINT Upper R/L ✓                           |
| 142                         | CONTROL ARM BUSHING Lower R/L ✓                  |
| 143                         | CONTROL ARM BUSHING Upper R/L ✓                  |
| 144                         | TIE ROD END Outer R/L ✓                          |
| 145                         | TIE ROD END Inner R/L ✓                          |
| 146                         | DRAG UNK / CENTER LINK / TIE-ROD ✓               |
| 147                         | IDLER ARM / PITMAN ARM ✓                         |
| 148                         | STABILIZER BAR / LINKS / BUSHING ✓               |
| 149                         | STRUT ROD BUSHINGS ✓                             |
| 150                         | SHOCK ABSORBERS Condition/Leak/Bushings R/L ✓    |
| 151                         | FRONT SPRINGS R/L ✓                              |
| 152                         | SPRING SHACKLES R/L ✓                            |
| 153                         | KING PIN BUSHING R/L ✓                           |
| 154                         | McPHERSON STRUT ASSEMBLY R/L ✓                   |
| 155                         | TORSION BAR R/L ✓                                |
| 156                         | P/S PUMP / HOSE Condition / Leaks ✓              |
| 157                         | P/S CONTROL VALVE / CYLINDER Operation / Leaks ✓ |
| 158                         | POWER STEERING FLUID Level ✓                     |
| 159                         | WHEEL BEARINGS Noise / Adjust ✓                  |

| SYMBOL EXPLANATION |   |                |   |
|--------------------|---|----------------|---|
| SATISFACTORY       | ✓ | UNSATISFACTORY | X |
| MARGINAL CONDITION | M | NOT APPLICABLE | - |


| COMPUTER TEST CODES |  |
|---------------------|--|
|                     |  |
|                     |  |
|                     |  |
|                     |  |


Comments/Estimate

---


Body Condition




Right




Left



Rear



Underside



Front

Date \_\_\_\_\_ Time \_\_\_\_\_

Signature \_\_\_\_\_

Lic. No. \_\_\_\_\_ Mech. \_\_\_\_\_

This estimate report is based on visual inspection only. Estimates given here do not include problems located upon disassembly of vehicle. Estimate good for 30 DAYS and inspection costs refundable on total repair.

P. 1/1  
 978 774 0558  
 7804630703 >>  
 Ragazzi Bistrot  
 2010-02-22 17:37